







03941814-0837-01









*Fig. 8*



*Fig. 9*




*Fig. 10*




*Fig. 11*

0941314-082701



*Fig. 12*



*Fig. 13*

05941814-082701




Fig. 14






Fig. 15



05941814-082701








Fig. 18





0941314-082701  
T07280-4T87450




Fig. 14(c)




Fig. 14(d)




FIG. 14(e)




FIG. 14(f)

Fig. 15(a)





Fig. 15(b)



0341844-032701





Fig.16 (a)








FIG. 17(b)




FIG. 17(C)

099441814-082/01










FIG. 17(d)

09414-03701  
T0280-4184650





094314-032701

TO/280"4T8T4660

100




Fig. 19




FIG. 20 (a)




FIG. 20 (b)




Fig 20(c)

05941814-082701






FIG 20(d)

0694314-082701





Fig.21(b)

0941814-082701




Fig 21 (c)

134

693

0941814-082701




FIG. 22(b)




FIG. 22(c)






FIG 22 (d)

09941814-082/01



09941814-082701




FIG. 23(a)




FIG. 23(b)

09941314-082/01






Fig. 24 (a)

0941814-082701

09441314-032701




Fig 24 (6)

09641314-032701




FIG. 24(c)




FIG. 25(a)




FIG. 25(b)

0941314.032701




FIG. 25(c)

0941314.082701




FIG. 26

094131-082701




FIG. 27

09541814-082701





FIG. 28(a')




094114-082701

FIG. 28(b)



09941814-082701



05941814.082701




FIG. 28(d)




FIG. 28(e)




FIG. 28(f)




FIG. 28(g)

0941314-082701  
10/22/2014 13:14:08




FIG. 28(h)

09541814-082701




FIG. 29

CONFIDENTIAL - OREGON




FIG 30(a)

09541814.082701





FIG 30(b)



0941814.082701



09941814-082701






FIG 32 (a)

0941814-082701



32(b)

0941814.082701



32(c)

FIG. 32(d)




FIG. 32(d)

09941814-082701




FIG 33(a)

107280-4T8T650




FIG 33(b)

0941314-032/01




FIG 33(c)



0941814-082701




FIG 34

0941814-082701

927 J






FIG 35 (a)

1140



09941814.082701




FIG 35(d)

0941814-082701




FIG. 36(a)

FIG. 36 (b)




FIG. 36 (b)

0941814-082701




FIG. 36 (C)

0941814-032701





FIG. 37(a)



0941814.082701






FIG. 38 (a)




FIG. 38 (b)

FIG. 38(c)






FIG. 38(c)

0941314-082701

FIG 39(a)



[illegible]

39 (b)

Fig. 40(a)

09941814.082701




FIG 40(b)

05941814.082701




FIG. 41 (a)




FIG. 41 (b)